


# Schedule of Accreditation

issued by

## United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <b>7686</b> Accredited to ISO/IEC 17025:2017	<b>AQUAPLUS LIMITED</b>  <b>Issue No: 010    Issue date: 01 December 2023</b>	
	<b>The Lodge Fairhill</b> <b>Charterhouse Road</b> <b>Godalming</b> <b>GU7 2AH</b> <b>United Kingdom</b>	<b>Contact: Mr Colin Jones</b> <b>Tel: +44 (0) 1483 428 612</b> <b>E-Mail: info@aquaplug-uk.com</b> <b>Website: www.aquaplug-uk.com</b>

Testing performed by the Organisation at the locations specified

Locations covered by the organisation and their relevant activities

Site activities performed away from the locations listed above:

Location details		Activity	Location code
<b>Address</b> All locations suitable for the activities listed	<b>Local contact</b> Mr C Jones	Testing Curtain walling, windows & glazing	Site



7686  
Accredited to  
ISO/IEC 17025:2017

**Schedule of Accreditation**  
issued by  
**United Kingdom Accreditation Service**  
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

**AQUAPLUS LIMITED**

**Issue No:** 010 **Issue date:** 01 December 2023

Testing performed by the Organisation at the locations specified

DETAIL OF ACCREDITATION

Materials/Products tested	Type of test/Properties measured/Range of measurement	Standard specifications/ Equipment/Techniques used	Location Code
CURTAIN WALLING RAINScreens SLOPE GLAZING	Water Penetration – Hose Test	CWCT Standards for Systemised Building Envelopes and Test Methods for Building Envelopes, December 2006  Section 9	Site
	Water Penetration – Spray Bar	Section 10	Site
	Hose Test	NHBC Standards 2023 Section 6.9.17	Site
	Sparge Bar Test	NHBC Standards 2023 Section 6.9.18	Site
WINDOWS and CURTAIN WALLING	Watertightness Site Test	BS EN 13051:2001	Site
	Hose Test	AAMA 501.2-15	Site
		NHBC Standards 2023 Section 6.9.17	Site
END			